ALPHA Y SERIES TOTAL STATION

User Manual(Ver1.0e)

Symbol

: Indicates the precautions and important contents that should be read before operating.

	:	Indicates the name of the chapter to be read by reference.
È.	:	Indicates a supplementary note.
	:	A description that represents a particular term or operation.
	:	Indicates the keys on the operating keyboard of this instrument.
[ENT] etc.	:	Indicates the software content displayed.
(Program)etc.	:	Indicates the name of the screen tip.
<program menu="">etc.</program>		

Models

This manual is applicable to ALPHA Y series total station produced and sold by ALPHA Co., Ltd.

Before using this instrument, it is important to check and confirm that all functions of the instrument are working properly.

Do not aim the instrument directly at the sun

Pointing the instrument directly at the sun can seriously injure the eyes. If the objective lens of the instrument is aimed directly at the sun, the instrument will also be damaged.

Set the instrument on a tripod

When setting up the instrument, use a wooden tripod if possible. The vibrations that may be caused when using a metal tripod can affect the measurement accuracy.

Install the tribrach

If the tribrach is not installed correctly, the measurement accuracy will also be affected. Always check the adjustment screw on the tribrach and make sure that the screw of the tribrach connecting to alidade is locked. The center fixation on the tribrach is screwed down.

Protect the instrument from vibration

When moving the instrument, it should be properly protected so that the impact of vibration on the instrument is minimal.

Tip pf the lifting the instrument

When lifting the instrument, be sure to grasp the handle of the instrument.

High temperature environment

Do not leave the instrument in a high-temperature environment for too long, otherwise this will affect the performance of the instrument.

Sudden changes in temperature

A sudden change in the temperature of the instrument or prism can cause a shortening of the range, like when the instrument is removed from a hot car, and the instrument should be left for a period of time to adapt to the ambient temperature before starting the measurement.

Battery check

Check the remaining battery capacity before working

Remove the battery

It is recommended not to remove the battery when the instrument is turned on. Otherwise, all stored data may be lost. Therefore, please install and remove the battery after the instrument is turned off.

Responsibility for in-memory data

ALPHA is not responsible for the loss of memory data caused by accidents.

When the EDM part of the instrument is working, the sound of the motor inside the instrument may be heard, which is a normal phenomenon and will not affect the operation of the instrument.

To ensure safe operation and avoid personal injury or property damage, this manual uses "Warning" and "Caution" to indicate the terms to be followed. Before reading the main content of this manual, please understand the meaning of these tips.



Warning : Ignoring this tip and incorrect operation may result in serious injury or death of the operator.



Caution : Ignoring this tip and incorrect operation may result in injury to the operator or property damage.

Precautions for safe use



 If the instrument is disassembled or repaired without authorization, there is a risk of fire, electric shock, or damage to objects.

Disassembly and repair can only be carried out by ALPHA and authorized dealers.

It can cause damage to the eyes or blindness.

Do not look at the sun with the instrument's telescope.

High temperatures may cause fire.

Do not cover the charger while charging.

• Risk of fire or electric shock.

Do not use bad power cables, plugs, and outlets.

• Risk of fire or electric shock.

Do not use wet batteries or chargers.

Explosions may occur.

Do not use the instrument close to burning gas and liquid, and do not use nonexplosion-proof total stations in coal mines.

- The battery may cause an explosion or injury.
 Do not leave the battery in a fire or high temperature environment.
- Risk of fire or electric shock.

Do not use chargers that are not specified by the manufacturer.

Risk of fire.

Do not use a power cable that is not specified by the manufacturer.

- A short circuit in the battery may cause a fire.
- Avoid short circuit when storing the battery.

Caution



- Do not disassemble and assemble the instrument with wet hands, otherwise there will be a risk of electric shock.
- Flipping the instrument case may damage the instrument. Do not stand or sit on the instrument case.
- Please note that the toes of the tripod may be dangerous, so be careful when erecting or transporting it.
- Falling the instrument or instrument case may damage the instrument.

Do not use a case with broken straps, buckles, or hinges.

- Do not touch your skin or clothing with acids flowing out of the battery, if you accidentally touch it, please wash it with plenty of water and carry out medical treatment.
- Be sure to install the tribrach correctly, otherwise, if the tribrach falls, it will cause injury.
- If the instrument is dropped, it will cause serious consequences.
 Please check that the instrument is properly attached to the tripod.
- Falling tripods and instruments can have serious consequences. Please check that the spiral on the tripod is tightened.
- When packing, the clamp locked may damage the instrument.
 When packing, check whether the clamp has been loosened.

User

1) The product should only be used by professionals.

The user must have a sufficient level of measurement personnel or knowledge of measurement in order to understand the user manual and safety instructions before using, inspecting, and calibrating the instrument.

Disclaimer

1) The user of this product should use it in full accordance with the instruction manual and regularly check the performance of the instrument.

2) The factory and the representative office shall not be liable for any direct or indirect consequences and loss of profits caused by destructive or intentional improper use.

3) The factory and its representative office shall not be liable for any direct or indirect consequences and loss of profits caused by natural disasters (such as earthquakes, storms, floods, etc.), fires, accidents or third parties.

4) The factory and the representative office shall not be liable for the non-working of the

product due to the change, loss, and interference of the data.

5) The factory and the representative office shall not be liable for the consequences and loss of profits caused by the failure to operate in accordance with this instruction manual.6) The factory and the representative office shall not be liable for the consequences and loss of profits caused by improper handling or connection with other products.

Safety standard for laser beam(ranging)

This series of total stations use a visible laser. This series of total stations is based on the "Performance Standards for Luminescent Products" (FD. BRH21CFR1060) and "Radiation Safety, Equipment Ratings, Requirements and User Guidelines for Laser Products" (IEC60825-1) which provide laser beam safety standards to manufacture and sell. According to the above standards, this series of products are "Class I laser products" in prism or reflector mode, and "Class III laser products" only when in reflectorless ranging mode.

Once the instrument fails, do not disassemble the instrument by yourself. Please contact ALPHA or dealer.

Safety standard for laser beam(laser plummet)

This series of total stations use laser plummets which adopt visible laser. This series of total stations' laser plummets are based on the "Performance Standards for Luminescent Products" (FD. BRH21CFR1040) and "Radiation Safety, Equipment Ratings, Requirements and User Guidelines for Laser Products" (IEC60825-1) which provide laser beam safety standards to manufacture and sell.

According to the above standards, this series of products are "Class II laser product".

Once the instrument fails, do not disassemble the instrument by yourself. Please contact ALPHA or dealer.

Sign

The following signs on this series of instruments remind users to pay attention to the safety of the laser beam.





Precautions for safe use of laser

• Follow the safety tips on the instructions or labels on the instrument to ensure safe use of this product.

• It is strictly forbidden to irradiate the laser beam into the eyes of others, otherwise it will cause serious injury.

- It is forbidden to look directly at the laser beam emitter to avoid permanent damage to the eyes.
- Do not stare at the laser beam to avoid permanent damage to the eyes.

• It is strictly forbidden to use optical instruments such as telescopes to view the laser beam, otherwise it will cause permanent damage to the eyes.

Content

1 Keys description	1
1.1 Panel keys	1
2 Battery Usage	2
2.1 Battery capacity	2
2.2 Battery replacement	3
2.3 Charge the battery	
3 Preparation for measurement	5
3.1 Center	5
3.2 Level up the instrument using laser plummet	5
3.3 Level up the instrument relying on the screen	8
3.4 Focus and collimate	9
4 User setting	
4.1 Enter user setting	
4.2 Correct the zero position of compensator	
4.3 Calibrate the collimation error and index error	
4.4 Target Management	
4.5 Light Management	
4.6 Unit Setting	
4.7 Backlight	
4.8 Connection	
4.9 Distance Const	
5. File management	
5.1 Enter SurPad measurement program	
5.2 Project Management	
5.3 Coordinate points database	
5.4 Export file	
6 Survey	

6.1 Detail Survey23
6.2 Coordinates for orientation setup24
6.3 Azimuth for orientation setup 25
6.4 Resection
6.5 Point survey
6.6 Radial opposite side measurement
6.7 Adjacent opposite side measurement
6.8 Remote height measurement with prism 32
6.9 Remote height measurement with reflectorless
6.10 Point stakeout
6.11 Line stakeout
6.12 CAD
6.13 Stake road by point41
7. Check and Adjustment 44
7.1 The Instrument Constant 44
7.2 Plate Level and Circular Level 45
7.2.1 Plate Level
7.2.2 Circular Level
7.3 The Optical Sight
7.4 Laser Plummet
7.5 Vertical Cross-hair on Telescope 49
7.6 Horizontal Collimation Error C51
7.7 Vertical Index Error52
8 Specification
Appendix 1 :Atmospheric Correction Formula and Atmospheric Correction Diagram (for reference only)57
Appendix 2 :Corrections for atmospheric refraction and the curvature of the Earth
Appendix 3 :Disassembly of the tribrach61



1 Keys description

1.1 Panel keys



Кеу	Name	Function
Ú	Power	Controls the power on/off of the instrument
0-9	Digit	When entering a number, input the number corresponding to the key
-	Minus sign	Input minus sign
	Dot key	Input dot/decimal point
*	Star key	Directly enter user settings page
BS	Backspace /Delete	Cursor backspace/Delete the last input character

2 Battery Usage

2.1 Battery capacity

Percentage of battery capacity is used to indicate the remaining battery capacity.

capaci	í -		
	Battery Level:29%	SimpleSurvey	Version:1.0.0.29
	Measure Program	User Setting	Exit
100% ↓ 30%	A Measurement is a	available	
Ļ	,		
20%	battery capacity i	s insufficient, please c	charge or replace battery.
↓ 10%	Measurement is un immediately	navailable, please char	ge or replace battery



- The length of battery operation depends on many factors, such as the temperature around the instrument, the length of charging time, and the number of times it is charged and discharged. Just in case, it is advisable to charge the battery or prepare a number of fully charged spare batteries.
- The battery percentage indicates the battery level in the current measurement mode. The battery level displayed in the angle measurement mode is not suitable for distance measurement. Since the power consumption of ranging is greater than that of angle measurement, when the angle measurement mode is changed to the distance measurement mode, the operation of the instrument may be interrupted due to low battery power.
- When the observation mode is changed, the battery percentage icon may not immediately show a decrease or increase in battery level. The battery percentage indicator system is used to show the overall condition of the battery level, it does not reflect the instantaneous change in battery level.
- It is recommended to check the power status of the random battery and spare battery before setting off for field measurement.

2.2 Battery replacement



- The battery should be removed when the instrument is not in use.
- Be sure to turn off the power before removing the instrument.

• Before installing or removing the battery, please pay attention to prevent water droplets or dust from entering the main unit.

• Regularly wipe the host power contacts with a cleaning cloth to ensure the cleanliness of the contacts.

► Steps

- Insert the guide block at the bottom of the battery into the battery guide hole on the instrument;
- 2) Tap inward on the top of the battery until you hear a click.



Remove the battery

1) Press and hold the button on the battery and press down on the unlock button.

2) Remove the battery outward.

2.3 Charge the battery



As shown in the figure above, connect the charger to the battery, then connect the charger adapter plug to the 220V AC power supply, the blue indicator on the battery flashes, indicating that it is charging, and after 6~8 hours, the blue indicator lights are always on, indicating that the charging is complete.

ኛ Hint:

• A new battery (or a battery that has not been used in months) needs to go through several charging and discharging processes to achieve optimal performance, please

charge it for at least 3 hours.

- If the battery needs to be charged to its maximum capacity, it is recommended to continue charging it about 30 minutes after the blue light is on.
- Indicator Status: Flashing blue light -- Charging; Solid blue light -- Charging completed.

• If the battery does not flash or glow blue after being plugged in, please remove the charger from the AC power source and wait a while before reconnecting it to the AC power source.

3 Preparation for measurement

3.1 Center

Steps

Place the tripod

Make the tripod legs equal in length, the tripod head is on the measuring point and approximately horizontal, and the tripod legs are firmly supported on the ground.

Set up the instrument

Place the instrument on the head of the tripod, hold the instrument with one hand, and tighten the central screw with the other.

The position of the measuring point and the laser point

By turning on the laser plummet, observe its position with the measuring point, and adjust the relative position appropriately.



3.2 Level up the instrument using laser plummet

Steps			
		User Setting	*
1)Power on	Till Method Dont Fix * Larer Plummet	TiltX:10'34.6" TIX	@
	HO O		Bubble
2)Press [★] to enter user settings	Brightness1 Brightness2	чит.	Tilt Zero Poa
2,	O Brightness3		\Rightarrow

3)When the laser plummet on the right side is displayed as "off", it means that the laser is off, the brightness of 1~4 means that the laser is on, and the larger the number, the brighter the laser



4) Adjust the laser plummet of the instrument so that it coincides with the ground mark



5)Center the circular level Repeat this by shortening the tripod leg closest to the bubble, or extending the tripod leg furthest from the bubble so that the bubble is centered.

6)Center the plate level Release the horizontal lock drive, rotate the alidade so that the plate level is parallel to the line of the footscrews A and B, and rotate the footscrews A and B to center the bubble, the bubble moves in the direction of the footscrew that rotates clockwise.

7)Rotate 90° to center the bubble Rotate the alidade 90° so that the level axis is perpendicular to the line of footscrews A and B, and rotate the footscrew C to center the bubble.

8) Re-rotate 90° to check the bubble

Rotate the alidade 90° again and check if the bubble is centered, if not, follow the steps below:

 Rotate the footscrews A and B in the opposite direction by the same amount,

so that the bubble moves half of the offset towards the center.

- (2) Rotate the alidade 90° and rotate the footscew.
- (3) Move the bubble towards the center by half of the offset.









• If none of the above steps can center the bubble, please correct the plate level.

Prefer to chapter "7.2 Plate Level and Circular Level"

9) Check that the bubble is in the same position in

any direction

Check that the bubble is in the same position in any direction, and if not, repeat the above steps for leveling.

10)Align the instrument with the measuring point

Loosen the center screw slightly, observe through the laser plummet, and carefully slide the instrument over the tripod head until the measuring point coincides with the laser point and tighten the center screw.

11) Check again to make sure that the bubble of the alidade is centered, if not, repeat steps after step (7).

3.3 Level up the instrument relying on the screen

- 1) Power on
- 2) Press [★] to enter user settings
- 3) Electronic level displays

"•" is the circular bubble of electronic level, the tilt range for inner and outer circles are respectively $\pm 3'$ and $\pm 6'$. The tilt angles of X, Y directions are also displayed on the screen.

4) Center the bubble

Refer to steps 5) and 6) in chapter "3.2 levelup"

5) Turn the alidade of the instrument so that the telescope is parallel to the line of footscews A and B, and then tighten the horizontal lock drive.

6) Rotate the footscews A and B to make the tilt angle value of X direction "0", and rotate the footscrew C to make the tilt angle value of Y direction "0".







7) Press [ESC] to end.

3.4 Focus and collimate



1) Evepiece focus

Use a telescope to look at a bright background. Rotate the evepiece clockwise all the way down, and then slowly rotate it counterclockwise until the crosshair image is the clearest.

2) Collimate the target

Release the vertical and horizontal lock drives, aim the target with the optical sight and bring it into the field of view, and tighten two lock drives



3) Objective focus

Rotate the telescope focusing ring until the target image is the clearest. Vertical and horizontal tangent screws are used to precisely align the crosshairs with the target. The final direction of rotation of the tangent screws should be clockwise

4) Focus again till no parallax

Focus again until there is no parallax between the target image and the crosshairs.

Note:

 When observe changing the face position, use the crosshairs to collimate the target at the same position.



Parallax

When the observer's eyes move slightly in front of the eyepiece, the alignment error caused by the relative displacement between the target image and the crosshairs is called parallax.

Parallax can cause errors in the observation readings and should be eliminated before observation. Parallax can be eliminated with correct focusing.

4 User setting

On this interface, you can set some functions commonly used by users.

Steps

4.1 Enter user setting

1) Power on

2) After the instrument automatically enters the SimpleSurvey interface, click the "User Setting" icon on the screen, or press the [*] button on any interface to enter the user setting interface

3)The electronic level is displayed on the screen, click the buttons under "Laser Plummet" on the right to turn on or off the plummet laser and adjust the brightness of the laser spot.

4) Click the [▼] button under "Tilt Method" on the upper right side to turn off or turn on the single-axis/dual-axis compensator.



4.2 Correct the zero position of compensator

After the instrument enters the user setting interface, click the "Tilt Zero Pos" icon on the left side of the screen, and the instrument enters the tilt zero position correction interface

After collimating the reference point at face left, click the "left face" on the screen, and then click the "Read Tilt" button on the right side.



After the instrument is rotated 180 degrees, collimate the reference point at face right, and then click the "right face" on the screen, and then click the "Read Tilt" button on the right side of the screen

	НА	205*20*23.4*	VA	240*48'41.1*	Read Tilt
۲	TiltX	-00'23.0'	TiltY	-00'33.9"	incore rint
Bubble	HA and VA only	for your reference			Calculate
	O Left Face		Right Face		Clear
(III)	Left TiltX	-00'16.5'	Left TiltY	-00'24.5"	_
It Zero Pos	Right TiltX	-00'12.8"	Right TiltY	-00'22.3"	Zero HA
	New TiltX Zero		New TiltY Zero		
	Old TiltX Zero	-00'07.0"	Old TiltY Zero	-00'03.1"	Save
nstrument					
20					
		Use	r Setting		
		205*20'25.0'	VA	240*48'41.1*	Read Tilt
•	HA				

Click the "Calculate" button on the right side of the screen and the instrument calculates the new tilt zero position value.

Click the "Save" button on the right side of the screen, the instrument pops up a prompt box, click "OK" to save the new tilt zero position, or click "Cancel" to cancel the new value.

4.3 Calibrate the collimation error and index error

After the instrument enters the user setting interface, click the "Instrument 2C" icon on the left side of the screen to enter the instrument collimation correction interface.

If you need to correct the instrument index error, click "Instrument VC" on the screen, and the method steps of two corrections are exactly the same.

After collimating the reference point at face left, click the "Left Face" on the screen, and then click the "Read Angle" button on the right.



After the instrument is rotated 180 degrees, and collimate the reference point at face right , click the "Right Face" on the screen, and then click the "Read Angle" button on the right side of the screen.

Click the "Calculate" button on the right side of the screen, and the instrument calculates a new collimation error/index error.

Click the "Save" button on the right side of the screen, the instrument pops up a prompt box, click "OK" to save the new collimation error/index error, or click "Cancel" to cancel the new values.

4.4 Target Management

After the instrument enters the user setting interface, click the "Target Management" icon on the left side of the screen to enter the target management setting interface.

Click Prism/NO Prism /Reflector/Remote Prism under "Select Target" to change the type of target irradiated by the instrument.

The instrument is equipped with a temperature and barometric pressure sensor, click the [Auto/Mechanic] button under "Weather Info" to select the instrument to enter the temperature and barometric pressure automatically or manually.





If you need to enter manually, click the field to be entered, enter the required value in the pop-up soft keyboard, and then click the [V] button to confirm the input.

Click the constant value under "Prism Const" to change the prism constant value in the pop-up soft keyboard.

After all the settings are complete, click the [Save] button on the right to save the current settings.

4.5 Light Management

After the instrument enters the user setting interface, click the "Light Management" icon on the left side of the screen to enter the light management setting interface.

Click the button below "Laser Point" to turn on/off the laser pointer, where:

Off: Turn off the laser pointer

Brightness 1: turn on laser pointer by low brightness

Brightness 2: turn on laser pointer by high brightness

Slide the [•] button below "Cross Light " on the screen to adjust the illumination brightness of the telescope reticle crosshairs, where "0" means to turn off the illumination, and the larger the " 1^{9} " number, the brighter the illumination.

Click the [On/Off] button under "Measure Distance Beep" to turn on or off the prompt sound when the instrument is used for ranging.

After all the settings are complete, click the [SAVE] button on the right to save the current settings











4.6 Unit Setting

After the instrument enters the user setting interface, click the "Unit Setting" icon on the left side of the screen to enter the unit setting interface.

Click the [▼] button to the right of the unit you want to set, and select the unit you want to set in the scroll down menu.

After all the settings are complete, click the [Save] button on the right to save the current settings.



Angle unit	DMS*, Degree, Rad, Gon, Mil					
Angle resolution 1 second, 01 second*,001 second						
Distance unit	Meter*, US-Feet, US-Inch, INT-Feet, INT-Inch					
Distance resolution	1 mm, 01 mm *,001 mm					
HAngle Type	RightAngle*, LeftAngle					
VAngle Type	ZA*, VA, HLR90, GR					

Unit setting items (the marked with "*" is factory default)

4.7 Backlight

After the instrument enters the user setting interface, click the "Backlight" icon on the left side of the screen to enter the backlight settings interface. Click button to turn on or off the left/right key backlight, as well as onescreen or double-screen display mode, where: Left Key Backlight: The backlight of the keys

at the bottom of the screen facing the user at face left will work

Right Key Backlight: The backlight of the keys at the bottom of the screen facing the user at face right will work

Show One Screen: The instrument only displays face-left screen, click to turn off the reverse side screen

Show Double Screen: The screens on both sides of the instrument are always on at the same time



4.8 Connection

After the instrument enters the user setting interface, click the "Connection" icon on the left side of the screen to enter the connection management setting interface.

Click the [] button to the right of the required settings, and select the option you want to set in the scrolling menu.



Connection setting items (The marked with " \ast " is factory default)

Baudrate of serial port	1200, 2400,4800,9600,19200,38400,57600,115200*
Profile(Protocol) of serial port	BASIC, GEOCOM*
Use of serial port	Use For Internal * , Use For External
Remote BT Port Profile(Protocol)	BASIC*, GEOCOM
Use of Remote BT Port	Use For Internal, Use For External *
Use of RTK Port	Use For Internal, Use For External *

4.9 Distance Const

After the instrument enters the user setting interface, click the "Distance Const" icon on the left side of the screen to enter the distance constant setting interface

After Selecting Target Type, you can set the constant of the currently set target type, click the "_" box after add/mul const, and enter the new value in the pop-up soft keyboard.





Click the [Measure Distance] button on the right side of the screen, the instrument can measure the current target, and the result is displayed at the bottom of the screen.

Tap the [Times Type] button on the right side of the screen to set the measuring times, and then click [OK] button when the setting is complete.

Tap the [Quality Type] button on the right side of the screen to set the quality type of the instrument, set the type to Fine /Coarse/Track, and then click [OK] button.

Click the [Get Return Light] button on the right side of the screen to view the return signal of the current instrument illuminating the target, and display the result at the "Return Light" at the bottom of the "Distance Result" column.

After all the settings are complete, click the [Save] button on the right to save the current settings.







)	NO Prism Const				Туре
	Add Const	0	Mul Const	0	Stop Measur
	Laser Point				measure
	 Off 	0	Brightness1	O Brightness2	Get Return
1	Distance Result				Light
	SD	1.8796	Return Light	21%	Backup UserP
					Restore

5. File management

5.1 Enter SurPad measurement program

Press the power button to turn it on.

After the instrument automatically enters the SimpleSurvey interface, click the "Measure program" icon on the screen to appear the interface on the right.

Click the SurPad icon on the screen, and the instrument will enter the startup interface, as shown in the right picture.

After the startup is complete, enter the right picture interface.

5.2 Project Management

The instrument is in the SurPad measurement program, after clicking the "Project" icon on the left, tap "Project Manager" on the screen to enter.



FOIF SurPAD

Under the Project Manager screen, tap the [New] button on the lower left side of the screen to create a new project.

Click the project name, in the pop-up keyboard the name of the project can be modified.

You can also enter the operator and remarks of the project as needed.

After sliding down the screen, you can select whether the current new project applies to the original project parameters. After completing the input, click [OK] button to confirm the new current project.

Select an item in the list of items on the screen, the item is shown in blue, click the [Open] button at the bottom of the screen, that is, the selected item is opened as the current instrument use item.

After entering the name of the item you want to find in the Find Item input box, click the [Q] icon on the right side of the screen for item search, and the found item will be shown in blue below.



Click the [Import] button at the bottom of the screen to import items into the instrument from the specified path.

Click the Export button at the bottom of the screen to export the currently selected project file to the specified path.

Click the [Details] button at the bottom of the screen to view the engineering project properties of the currently selected project.

5.3 Coordinate points database

The instrument is in the SurPad measurement program, after clicking the "Project" icon on the left, click " Points Database " on the screen to enter.

The instrument displays all coordinate points under the currently opened item.





÷	← Points Database									
Co	unt 2		hs	ut name o	r code			Q	T	≡
	Name	Northing	Easting	Elevation	Anterna	Measurement Typ	e Anten	na Measured	Height /	intenna Height
Ŷ	Pt2	20.000	20.000	20.000						
Ŷ	Pt1	10.000	10.000	10.000						
	4	٨dd		Edit	:	Details		Imp	ort	

Click the icon $[\equiv]$ in the top right corner of the screen to toggle the list of coordinates displayed.

Click the icon [^{TE}] in the top right corner of the screen to filter the attributes of the list of coordinates displayed.

Enter the coordinate name you want to find in the Find items input box, click the [Q] icon on the right side of the screen to search for items, the found coordinate points are displayed below.

Click the [Add] button at the bottom of the screen to create a new coordinate point, enter the coordinate, code and property of the new point in the pop-up interface, and click the [OK] button at the bottom to confirm the adding.

Click a point in the list displayed, and the selected point will be displayed in yellow on the screen.

Click the [Edit] button at the bottom of the screen to edit the currently selected coordinate point, after editing, click the [OK] button at the bottom to confirm the modification.

Click the [Details] button at the bottom of the screen to view the details of the currently selected coordinate point.



Click the [Import] button at the bottom of the screen, you can import the coordinate data of other positions into the current project of the instrument.

After selecting the format and storage location of the imported coordinate file, click the [OK] button below, and the coordinate data in the selected file will be imported into the current project of the instrument.

Click the [...] button at the bottom of the screen, select the "Delete" option in the pop-up option box, you can delete the coordinate points in the current project.

Select the point you want to delete in the display list, and click the [Delete] button at the bottom of the screen when the selection is complete.

Click the [OK] button to confirm the deletion of the currently selected coordinate point, and click the [Cancel] button to cancel the deletion.

5.4 Export file

The instrument is in the SurPad measurement program, after clicking the "Project" icon on the left, click " Export File " on the screen to enter.



Click "Select Data File" to replace the data file you want to export.

Select the data file you want to export in the list display that pops up.

Click the [Format Manager] button at the bottom of the screen to select the data format of the exported file.

Click the [Export] button at the bottom of the screen, after selecting the storage location of the exported data, click the [Export] button at the bottom again, and the selected data file is exported to the specified location.



Select data	file		20231238.PD
Export Roo	File Format		
	TPS Survey point dat	0	
File Forma	Cass format(.dat)	○ ^{sv) >} (•	
[Point Name [SD].[HD].[V east].[Static	Local coordinates for	mat(.dat)	oordinate
Angle form	AutoCAD formatic duf	1	do'mmiss.ssss*

~	Export File
Internal Storage/Su/Pad/Export	G
${\bf k}_{\rm b}$ Go to internal storage root directory	
K Go to program storage directory	
🔦 Return	
File Name	20231208153622
File Type	TPS Survey point data format(*.csv)
	Export

6 Survey 6.1 Detail Survey ► Steps

The instrument is in the SurPad measurement program, and the orientation setting has been finished, click "Survey" icon and "Detail Survey" to enter.

Click Orientation Setup to enter, click "Set backsight" option.

Select Coordinate Type in the pop-up option box.

Click the [(1)] icon to the right of Occupy Pt and Backsight Pt to select the coordinate point inside the database for calling.

≡ 2023	1208				() â
Project	2	Point Survey	>	\$	Detail Survey	>
Pioject	~	CAD	>	N.	Point Stakeout	>
Device		Line Stakeout	>		Stake road	>
0	<u></u>				Cross section	
Survey	<u>R</u>	Stake road by point	>	<u>a</u> D	measurement	>
× Tools		Stake road by bridge section	>	2	Conical Slope Stakeout	>
	-27	Ph		U	Electric Towers	
← 🔋		X-1		×	×	
Danez		2051804.3531	VA	the flow	an Duristerada 26421	939,3101*
N		203 10 04 03 51	SD		540 1	
F			HD			
h				tion diff.		
n			Fleva	eon ann.		
Name					\sim	Ptt 🕄
Code					(🧟)@
Target height					C	Cen >
		Setti	1gs			
← 😫		X				
HA		205*2121.8531*	VA	2111 Ne	asare Etertistion ant 45	*1217.416*
N		5 235	SD			2.769
E		8.004	HD			2.111
h		NaN	Elev	ation diff		1.822
Name						pt3
					6	
Code					9)@
Target heigh	t				C	an >
		Sett	ings			
← 🔋		<u>8-4</u>		Ş.		
Streed		Newspe		finge Me	nter Dietsimme	
HA		205'21'23.8531'	VA		49	12'10.2128*
N		5.236	SD			2.789
E		8.034	HD			2.111
h		NaN	Elev	ation diff		1.812
Name					\sim	pt4
Code					(🖗	
Target heigh	t				Ċ	\mathcal{I}_{2m}
←	_	Device	Settin	gs		
AGE Limit						5 >
Allow same	point na	me				
Point Name	ingreme	ent				
Default Code	,				same as	last point >
Average GPS	s Count					1>
- 0	ofault	Configurations		_	ок	_
	erauti	oomigatations			UK	

6.2 Coordinates for orientation setup

The backsight orientation azimuth can be calculated by occupied point coordinate and backsight point coordinate.



Steps

The instrument is in the SurPad measurement program, after clicking the "Device" icon on the left, tap "Orientation Setup" on the screen to enter.

Once you are in the orientation setup screen, click on the "Set backsight" column on the screen.

Select the "Coordinate Type" option inside the option box that pops up.

Click the [^(G)] icon to the right of Occupy Pt and Backsight Pt to select the coordinate point inside the database for calling.



← Orient	ation setup	
Instrument height	2.0	Confirm
Decupy Pt		6
Northing		7.144
Easting		8.906 😳
Elevation		NaN
Set backsight		Conclusive Type
		0

÷	Orientation setup			
Instrumen	height	2.0	Co	nfirm
Occupy Pt.	Set backsight			6
Northing	Coordinate Type		0	7.144
Easting	Azinuth Type		0	8.908 😳
Devation	Back Cross		0	NoN
Set backs	ght		Coordi	ate type 🗦
				6
	Reset Station			

← Points Database											
0.	unt S		Ing	ut name o	roode				Q	T	≡
	Name	Northing	kastng	Mexation	Antenna	Measure	nont Type	Antoni	a Measuras	Hoght a	Antonna Hoight
ę	pt3	5.236	8.004	0.000							
Ŷ	Pt2	20.000	28.000	20.000							
Ŷ	P0	13.000	18.000	10.000							
	,	\dd		Edir	;		Details		o	к	
After entering or calling coordinate data of the occupied point or backsight point, click the [Calculate] button below.

At face left rotate the instrument to collimate the backsight point and click the [Observe] button.

The instrument displays the orientation measurement result. Slide down the screen to view the measurement data. If the data is wrong, you can re-observe the correct backsight point and then click the [Observe Again] button below to measure again.

If the measurement is correct, click the display bar of "Setting Type" on the screen.

Select the option of "Set Direction" in the popup option box, click the [Accept] button at the bottom of the screen, and the orientation setup of the station is completed.

6.3 Azimuth for orientation setup ► Steps

The instrument is in the SurPad measurement program, after clicking the "Device" icon on the left, tap "Orientation Setup" on the screen to enter.

← Orie	ntation setup
Northing	20
Easting	20
Elevation	20 😳
Result	ω is
HAR	231''15 19.8036'
HD	11.419
Plaase any hooksight	
R	eset Station
← Orie	ntation setup
Northing	20
Easting	20
Elevation	20 😒
Result	
HAR	45
HD	14.142
Please aim backsight	
Cancel	Observe
← Orie	ntation Result
Backsight Observations	
на	205'21'21.0407'
VA	49'02'05.5098'
SD	2.778
HD	2.778
н	2
Accept	Observe Again
мссері	Observe Again
← Orie	ntation Result
Dist Fror	12.045
Calc Elev	11.821
Eler Enor	-8.179
Plate Settinga	
Setting Type	Set Direction
Azimuth	45'00'00'
Accept	Observe Again
← Orie	ntation Result
Dist Error	12.045
Calo Elev Setting Type	11.821
Elev Error Set Zero	O -8.179
Plate Setting Set Direction	o
Setting Ty Not modified	O Direction >
Azimuth	45°00'00'
Accept	Observe Again



Once you are in the orientation setup screen, click the "Set backsight" section on the screen.

Select the "Azimuth Type" option inside the option box that pops up.

Click the [(a)] icon to the right of Occupy Pt to select the coordinate point inside the database for calling

After entering or calling the coordinate data of the occupied point and the azimuth to the backsight point, click the [Reset station] button below.

To enter 120°47 '23 ", please input 120.4723.

At face left rotate the instrument to collimate the backsight point and click the [Observe] button.

The instrument displays the orientation measurement result. Slide down the screen to view the measurement data. If the data is wrong, you can re-observe the correct backsight point and then click the [Observe Again] button below to measure again.



Count 3		Inp	ut name o	code			Q	T	≡
Name	Northing	Easting	Devation	Antenna M	/easurement 7	yae Anter	ina Measured	Height	Artenne Heigi
🦻 p13	5.236	8.004	0.000						
Pt2	20.000	20.000	20.000						
🖗 Pt1	10.000	10.000	10.000						

÷	Orientation setup
Elevation	10
Set backsight	Azimuth Type 🗦
Azimuth	30 😳
Result	
HAR	23111619.8036*
HD	11.419
Please aim backsight	
	Reset Station

← Orientation setup				
Elevation		10		
Set backsight		Azimuth Type 🗦		
Azimuth		300 🕄		
Result				
HAR		30		
HD		11.419		
Please sim backsight				
Cancel	Accept	Observe		

÷	Orientation I	Result
Backsight Observations		
HA		205*20*51.8533
VA		49102105.5098
SD		2.77
HD		2.77
н		
нт		
	Accept	Observe Again

If the measurement is correct, click the display bar of "Setting Type" on the screen.

Select the option of "Set Direction" in the popup option box, click the [Accept] button at the bottom of the screen, and the orientation setting of the station is completed.

← Orientatio	on Result
Dist Error	-2.098
Calc Elev	11.822
Elev Error	11.822
Plate Settings	
Setting Type	Set Direction 🗧
Azimuth	30'00'00'
Accept	Observe Again
← Orientati	on Result
Dist Error	-2.098
Calc Elev Setting Type	11.822
Elev Error Set Zem	O 11.822
Plate Setting Set Direction	Ø
Setting Typ Not modified	O Direction >
Azimuth	30*00/00*

6.4 Resection

Install the instrument on the selected new site, calculate the new coordinates with the coordinates of up to 3 known points and the measurement data of these points, the known coordinate data entered during the measurement of resection and the calculated occupied point data can be stored in the current project.



Steps

The instrument is in the SurPad measurement program, after clicking the "Device" icon on the left, tap "Orientation Setup" on the screen to enter.

Once you are in the orientation setup screen, click on the "Set backsight" column on the screen.

Select the "Back Cross" option inside the option box that pops up.

After directly inputting or calling coordinate data of coordinate point A, at face left rotate the instrument to collimate coordinate point A, click the [*] button on the right side of L1 column on the screen,

After the measurement is finished, the measurement value will be displayed in L1 column.

After inputting the coordinate data of coordinate point B in the same way, proceed to measure the coordinate point B.

After the measurement is completed, click the [Calculate] button at the bottom of the screen, the instrument will automatically calculate the coordinate data of the occupied point. If you need to add the measurement point, click the [Add point] button, if not, click the [accept] button.

_	1208					. C	6
Project	0 2	Communication	>	њ	Parameter	Setting	s >
Device	83	Orientation setup	>	%	Reflector s	etting	>
	8	Level/Plummet	>	C+	More		>
Survey							
Tools							
÷		Orien	tation se	tup			
nstrument	height				2.0	Co	nfirm
ocupy Pt							7.144
Easting							8.908 😳
levation							NuN
Set backsig	pha					Coordin	ate Type 🗦
		Re	set Statio	n			0
.		Orien	tation se	tup			
nstrument	height				2.0 ©	Co	nfirm
Set backs	Setback	aght					ck Cross 🗦
int A	Coordi	nate Type				0	v (3)
lorthing	Azimu					0	Northing
levation	Back C	loss				•	Easting
		_			_		r©n
		Accept			Calculat	e	
-		Orien	tation se	tup			
et backsig	plat					De	ick Cross
int A forthing							~ ®
asting							10
levation							10 🕄
1						L1	8
int B		Accept			Calculat	e	× (6)
-		Orier	tation se	etuo			
et backsiç	yht.					B	ack Cross
int A							v ()
lorthing							ho ©
asting							10
levation						2.09	10 : [8]
at B		Accept			Calcula		× (6
-			ntation s	etup			
						2.0	/8 <u>1</u>
vin D							~ (
Easting							20 (
levation							:
.2						1.21	1 [8
coupy Pt Co	sordinate						
		Accept			Calcul	ate	
← Northing	Error	Orie	intation :	setup			
Easting B	rror						
Decupy Pt C	Coordinat	e					78.47141
HAR Northing							78,47141
Easting Elevation							11.6
Elevation Elev Error							8.
	Recalcu	late	Accept			Add Po	

Click the [OK] button to store the current coordinate data of the occupied point into the coordinate point database

After entering the point name and code data of the new occupied point, click the [OK] button below, the resection setting is completed, and the instrument will automatically return to the menu display.

6.5 Point survey

After the orientation setup completed, you can measure the three-dimensional coordinate of the target point.



Steps

After the instrument is in the SurPad measurement program and the orientation setting has been completed, tap "Point survey" on the screen to enter after clicking the "Survey" icon.



After turning the instrument to look into the point to be measured, press the [MEAS] measurement key on the side of the instrument or the [[®]] button on the screen to measure.





After the measurement is completed, the instrument displays the measurement data of the measurement point.

Slide down to check and confirm all the measurement data of the measuring point are correct, click [OK] button to save the point data to the coordinate point database.

	nt
Name	p84
Code	tree 🛇 👻 🥝
Target height	2m
letal information	
Record	<1/1>Collecter
Northing	12.27
Easting	21.7%
Photo And Sketch	
Photo And Sketch	
	t
← Topa Pain	t 21.743
C Topo Poin Easting Revalion	t 21.783 18.032
C Topo Poin Easting Devation MA	t 21.748 18.322 76*431,929
Easting Providen MA VA SD	t 27,793 18,352 78*4431,929 82*4232,687* 8388
Easting Providen MA VA SD	t 27.748 18.222 76-4131.9297 82-4232.6677 7.848 1.2421 2.3481 2.3481
C Topo Point	

6.6 Radial opposite side measurement

The radial opposite side measurement is the direct measurement of the slope distance, horizontal distance and vertical distance between multiple target points and a certain starting point without moving the instrument.



The instrument is in the SurPad measurement program, after clicking on the "Tools" icon on the left, click on "Opposite Side " on the screen to enter.

Collimate the starting point, click Observe to start measuring, then it will show the measurement result

≡ 2023	31208				9	â
	<u>.</u>	Augue conversa	<i>.</i>		F CHINGLE HARD ALCO	ĺ.
P roject	4	COGO Calculation	>		Calculator	>
Device	% ⊲	Opposite side	>	۲*	Remote height	>
Survey	110	FTP Shared Data	>	2	Share File	>
A ourroy	Ŵ	Slow Bending Calculation	>	۲	lonosphere TEC	>
🗙 Tools	7	More	>			

Opposite	New station	Observe
на		HA
Measure		
Slope		Slope
Horizontal distance		Horizontal distance
Height Error		Height Error
Slope distance		Slope distance
Result		
	Opposite side	

Look at the target point and click the [opposite] button to measure the target point. The screen displays the measured values as follows:

Slope distance: the slope distance between the target point and the starting point.

Height Error: The height error between the target point and the starting point.

Horizontal distance: The horizontal distance between the target point and the starting point.

Slope: The slope between the target point and the start point.

Look at the next target point and click the [opposite] button to measure the target point. Measure the slope distance, horizontal distance, height difference and slope

between multiple target points and the starting point in the same way.

6.7 Adjacent opposite side measurement

The target point of the last measurement can be set as the starting point of the subsequent measurement.

Steps The instrument is in the SurPad measurement

program, after clicking on the "Tools" icon on the left, click on "Opposite Side" on the screen to enter.

Collimate the starting point, click "Observe" to start measuring, the instrument shows the measurement result.

÷	Opposite side	
Result		
Slope distance		1.584
Height Error		-0.004
Horizontal distance		1.584
Slope		-0.23%
Measure		
HA		78'44'34.1092'
Opposite	New station	Observe

÷	Opposite side	
Result		
Slope distance		2.09
Height Error		0.013
Horizontal distance		2.09
Slope		0.633%
Measure		
HA		78°44'35.2031'
Opposite	New station	Observe

HA	pposite			w statio		Observe	HA
Measure							
Slope							Slope
Horizontal distance Horizontal distance							
Height Erro	r					Heig	ht Error
Slope distance Slope distance							
Result							
÷			Орр	osite si	de		
X Tools	C+	More		>			
	Ŵ	Slow Ben Calculation		>	۲	Ionosphere TEC	>
Q Survey	FB	FTP Shar	ed Data	>	R	Share File	>
Device	\$⊲	Opposite	side	>	X	Remote height	>
Project		COGO Ca	lculation	>		Calculator	>
	<u>.</u>	Angle of	menter	<i>´</i>	30005		ĺ.







Look at the target point and click the [opposite side] button to measure the target point. The screen displays the measured values as follows:

Slope distance: the slope distance between the target point and the starting point.

Height error: The height error between the target point and the starting point.

Horizontal distance: The horizontal distance between the target point and the starting point.

Slope: The slope between the target point and the start point.

Look at the next target point and click [New station] button, the instrument will eject a prompt box asking whether to change the starting point, click [OK] button, the current target point has been set as the starting point of the subsequent measurement.

Look at the new target point, click the [opposite] button to start the measurement, repeat the above steps to continue the opposite side measurement.

6.8 Remote height measurement with prism

There is a remote height measurement with prism for objects on which prism cannot be set, such as high voltage transmission lines, suspended cables, bridges, etc.



÷					
Result					
Slope distance	Pror	npt	0.694		
Height Error	teight Error Set last point 9.128 12.157 10.806 as starting point?				
Horizontal distance	contal distance Cancel OK		0.694		
Slope					
Measure					
НА			292*00'45.6827*		

÷	Opposite side	
Result		
Slope distance		0.694
Height Error		0.015
Horizontal distance		0.694
Slope		2.116%
Measure		
HA		292*00'45.6827*
Opposite	New station	Observe

Steps

The instrument is in the SurPad measurement program, after clicking the "Tools" icon on the left, click "Remote Height" on the screen to enter, and set up the prism directly below the point to be measured.

						_
≡ 202	31208	Angle contenter	,			Ô
Project	A	COGO Calculation	>		Calculator	>
Device	2	Opposite side	>	₹*	Remote height	>
👷 Survey		FTP Shared Data	>	2	Share File	>
-Scivey	Ŵ	Slow Bending Calculation	>	æ	Ionosphere TEC	>
🗙 Tools	7	More	>			

Under the remote height measurement interface, click the [Reflector Setting] button in the lower right corner of the screen to set the prism.

After setting the reflector to "Prism" and entering the parameters for currently erect prism, click the [OK] button.

Look at the prism, click the [Observe] button to start the measurement, the measurement is completed and the measurement result is displayed.

Turn the instrument to look at the point to be measured and click the [Remote height] button. After the measurement is completed, the screen will display the height of the point to be measured.

← Remote heigh	t
Result	
Remote height	2
Measure	
на	78*4458.5155*
VA	14'50'22.8037'
SD	ö
HD	0
Observe	Reflector setting
← Reflector settin	g
	-
Reflector	Prism 🗦
Prism height	2 🕄
Prism Constant(mm)	0
Prism Type	Standard Prism 🗦
ОК	
← Remote heigh Result	t
Remote height	2
Maasure	
HA	78*44*56.8281*
¥A.	14"50"22.8037"
SD	0
HD	0
Observe	Reflector setting
← Remote heigh	t
desult	
Remote height	2.375
ñeosure	
HA	78*44*59.6093*
VA	59*21'01.7149*
SD	2.813
HD	

6.9 Remote height measurement with reflectorless

Remote height measurement with reflectorless is used to directly measure the height from the ground projection point of the measured object to this measured point.



Steps

The instrument is in the SurPad measurement program, after clicking the "Tools" icon on the left, tap "Remote height" on the screen to enter.

Under the remote height measurement interface, click the [Reflector Setting] button in the lower right corner of the screen to set the target.

After setting the reflector to "Reflectorless" and setting the reflector height to "0", click the [OK] button.

Look at the projection point on the ground directly below the point to be measured, click the [Observe] button to start the measurement, and the measurement result will be displayed after the measurement is completed.

Turn the instrument to look at the point to be measured, click [Remote height] button, after the measurement is completed, the screen will display the height of the point to be measured.

					_	
≡ 202:	31208	Angle contenter	,	<u></u>		ŝ
Project	4	COGO Calculation	>	-	Calculator	>
Device	K	Opposite side	>	X+	Remote height	>
Survey		FTP Shared Data	>	R	Share File	>
Sarrey	Ŵ	Slow Bending Calculation	>	6	Ionosphere TEC	>
🗙 Tools	7	More	>			

÷	Remote height
Result	
Remote height	3
Measure	
HA	78*44'59.0155*
VA	5912101.5117
SD	2.813
HD	2.813
Observe	Reflector setting

÷	Reflector setting
Reflector	Reflectoriess >
Prism height	3 😳
Prism Constant(mm)	0

÷	Remote height
Result	
Remote height	3
Measure	
на	78*44'59.0155*
VA	59°21'01.5117'
SD	3.526
HD	3.526
Observe	Reflector setting

÷	Remote height
Result	
Remote height	5.053
Measure	
на	78"44"58.828"
VA	38*13'32.5076*
SD	3.526
HD	3.526
Observe	Reflector setting

6.10 Point stakeout

After the coordinates of the stakeout point are given, the instrument automatically calculates the angle and distance values of the stakeout, and the position of the stakeout point can be measured by using the angle and distance stakeout function.



In order to determine the Z coordinate, the target is set on an object such as a measuring rod at the same height.



After the instrument is in the SurPad measurement program and has completed the orientation setting, click the "Survey" icon on the left and click the "Point stakeout" on the screen to enter.

The instrument enters point selection list and click on the stakeout point to be selected. If you do not have the required stakeout point coordinates in the list, click the [Add] button at the bottom left of the screen.

Enter the coordinates of the staked out point on the New point page, and then click the [OK] button at the bottom.



After selecting a stakeout point, the status bar of the point is displayed in yellow, and click the [OK] button at the bottom right of the screen to perform the stakeout step of the selected point.

Turn the alidade of the instrument so that the displayed "Setting out angle difference" value is "0° 00 ' 00", and set the prism to the collimated direction. Click the "Measure" button at the top of the screen to start measuring. The difference between the measured distance and the stakeout(setout) value is displayed on the screen, where: Backwards : Move the prism towards the station Forwards : Move the prism towards the station To left : Move the prism to the left To right : Moves the prism to the right

Cut¹: indicates higher than the stakeout elevation Fill¹: indicates lower than the stakeout elevation

When you command the prism to be placed by left and right, front and back, cut and fill until the allowable error for angular difference values, the setout of the current stakeout point is completed. Click the Next Point button on the right side of the screen to continue the measurement of the next stakeout point, and click the Points database on the left side of the screen to return to the list of Points database. Click the Add stakeout Point button to add

the coordinates of the stakeout points that are not available in the coordinate points stakeout.

6.11 Line stakeout

Line stakeout is used to stake out the points where the distances from the determined baseline are known, and can also be used to calculate the distance from the measured point to the baseline.











After the instrument is in the SurPad measurement program and the orientation setting has been completed, click the "Survey" icon on the left and click "Line stakeout" on the screen to enter.

The instrument enters the list of lines database, and please click on the bottom left of the screen [Add] button to enter the straight line parameter input interface.

After entering the name of the line and the start station mileage, select the input method of the line in the pop-up window in the input method field.

When you select the "Start point + End point" input method, scroll down the screen to enter the coordinates of the start and end points directly or select the start and end points from the list, and then click the [OK] button at the bottom.

When you select the "Point + Azimuth+ Length" input method, scroll down the screen to directly enter or select the coordinates of the starting point, the azimuth angle and length of the line, and then click the [OK] button at the bottom.



The instrument returns to the line database, click to select the line you just entered, and then click the [OK] button at the bottom right of the screen.

Enter the stakeout settings interface, select the stakeout interval and other parameters as needed, and then click the [OK] button at the bottom of the screen

At this time, the deviation of the measured point from the baseline is displayed on the screen, collimate the prism and click the "Measure" icon at the top of the screen, then the screen will update the deviation value from the measured point to the baseline, where:

Backwards 🖊: Indicates that the measured point is in front of the baseline

Forwards ¹: Indicates that the measured point is behind the baseline

To left 🚝: Indicates that the measured point deviates

from the baseline to the right

To right \Rightarrow : Indicates that the measured point is left away from the baseline

Cut 🖳 Indicates that the measured point is above the baseline

Fill : Indicates that the measured point is located below the baseline

Click the Select Target button on the right side of the screen to enter a new stakeout station in the input box that pops up.



No.	Line Name	Start Station	Length	Azimuth			
1	Pt1_Pt2	0.000	3	30100.001			
	Insert	E	dit	Delete	Share	ок	
							-
÷				Stakeout Se	ttings		
Setting out by pile by coordinate							

Stakeout by station number

Station

Interval/m)

Lines Database



01



6.12 CAD

This is the function such as processing and stakeout for CAD drawings stored on the instrument

Steps

After the instrument is in the SurPad measurement program, click the "Survey" icon on the left and click "CAD" on the screen to enter. It will prompt whether to load the last CAD drawing, click OK to confirm or No to cancel.

The instrument will display the loaded CAD drawing.

Click the zoom in or zoom out buttons to adjust the drawing display.



Click the button to do settings for display information.

Display Information					
CAD SETTING	TOOLBARS				
Display Item	Options				
⊖ Zoom out	>> Follow				
Zoom in	Optimized a state of the sta				
Jump map center	K Tr Antenna Parameters				
C Full Map	CAD Text				
- Andrew -	17 Augustus				
DEFAULT	ок				

Click the [Data] button at the bottom left of the screen to edit the drawing.

Click the "Layer" button to set the layer of the drawing.

Click the "Open" button to select a storage location within the instrument to open a new CAD drawing.

Click the "Export" button to export the currently opened drawing according to the settings.

Click "CAD Unit" to set the drawing unit.

Click "CAD Coordinate System" to set the coordinate system of the drawing.

38



Click the [Drawing] button at the bottom of the screen to draw the current drawing.

Click the [Survey] button at the bottom of the screen to measure the object selected in the current drawing.

Click the [Tools] button at the bottom of the screen to edit the current drawing using the tools on the screen.

After clicking on the screen to select a point or block, the edit bar will pop up at the bottom of the screen, and you can edit the point or block accordingly as needed.

Click Details to view the feature information of that point.

Click Delete to delete the point on the drawing



Click Explode to explode the selected block on the drawing

Click List to display the feature information of that point or block in the list.

Click "Stakeout" to enter the stakeout settings, and click the [OK] button below to stake out the selected points after the settings are completed

The instrument enters the stakeout interface, please refer to the specific operation steps of chapter **6. 10 Point stakeout**.

Click the "Capture" button on the right side of the screen, and the black dot and arrow shown on the right will appear on the screen.

After dragging the origin point on the screen so that the arrow points to a point, the instrument displays the stakeout data of that point.



						Object Info	
Er	ntity						polyline
La	iyer						0
No.	Name	Northing	Easting	Elevation	Code		
0	с	10.535	36.529	0			
1	N1	22.557	31.75	0			
2	N2	4.565	21.497	0			
3	N3	-1.488	37.485	0			
		Save				Modify	Stakeout

← Stakeout Setting	s
Setting out centre point	
Start Station	Start Station
Offset Distance	0
Setting out by pile by coordinate	







6.13 Stake road by point

By entering centerline, vertical profile, or various other elements on the instrument, the stakeout is carried out point by point according to the requirements through calculations



Steps

The instrument is in the SurPad measurement program, click the "Survey" icon on the left, tap "Stake road by point" on the screen to enter.

The instrument enters the interface of "Stake road by
point", and click the [New] button at the bottom left to
create a new road.





←		Road Design	
Road	Name		Road Name
ø	Broken station		>
¢	Centerline		>
۵	Vertical Profile		>
ø	Standard Cross Section		>
ø	Slope section Library		>
	Мар	Check	ок



Enter the road design interface and click the " centerline" column.

The instrument enters the centerline element input interface, and after confirming that the road design method is "line element method", click the [Add] button in the lower left corner. Enter various centerline features as needed.

Until all centerline features have been entered.

Click the [Calculate] button at the bottom of the screen to view the coordinates list of each pile on the road.

After entering all the vertical profile features using the same method as necessary, click the [OK] button.

Enter a road name in the Road Name field.

Click the [Map] button in the lower left corner to preview the centerline.

42

62.00 700.000 84.855 9.000 9.944799.9002* 62.00 720.000 44.974 9.111 0 9.94299.9567 64 755.000 69.911 4.48 0 9.9779.9507 5.557 Certical Profile Database Colspan="4">Certical Profile Database Colspan="4">Colspan="4" Colspan="4">Colspan="4">Colspan="4" Colspan="4">Colspan="4" Colspan="4" Colspan="4" Colspan="4" Colspan="4" Colspan="4" Colspan="4" Colspan="4" Colspan="4" <td <<="" colspan="4" th=""><th>÷</th><th>_</th><th></th><th></th><th>Line eler</th><th></th><th></th><th></th><th></th><th></th><th></th></td>	<th>÷</th> <th>_</th> <th></th> <th></th> <th>Line eler</th> <th></th> <th></th> <th></th> <th></th> <th></th> <th></th>				÷	_			Line eler						
targh 53 Azrnah Not 0K Hedrog Interfaced Interfaced Azrnah Social Social Azrnah Not Interfaced Azrnah Social Social Social Social	Line	Туре									Carve				
targh 53 Azrnah Not 0K Hedrog Interfaced Interfaced Azrnah Social Social Azrnah Not Interfaced Azrnah Social Social Social Social	Еста														
Annuh 30 000 Hoding Nazz OK Legin Metrico Lester Harring Satoria 1 barring Satoria Satoria 2 barring Satoria	Start	Radius									3				
Add Certer/I Add Edit Oalera Add Oalera Arran Statio Statio Oalera Statio Oalera	Leng	,th									5				
Next DK Centerline Instrument method Law Toos Devision Stars Bases Database Instrument method Law Toos Devision Stars Bases Database Instrument method Instrument method Law Toos Devision Stars Bases Database Instrument method Instrument method Add Edit Devise Calculate Instrument Stars Stars 0 Stars Stars Stars Instrument Stars Stars 0 Stars Stars Stars Instrument Instrument Stars Stars 0 Stars Stars Instrument Instrument Instrument Stars Stars 0 Stars Stars Stars Stars Instrument Stars Stars Stars	Azim	nuth									36 🖸				
Next DK Centerline Instrument method Law Toos Devision Stars Bases Database Instrument method Law Toos Devision Stars Bases Database Instrument method Instrument method Law Toos Devision Stars Bases Database Instrument method Instrument method Add Edit Devise Calculate Instrument Stars Stars 0 Stars Stars Stars Instrument Stars Stars 0 Stars Stars Stars Instrument Instrument Stars Stars 0 Stars Stars Instrument Instrument Instrument Stars Stars 0 Stars Stars Stars Stars Instrument Stars Stars Stars	Head	tina									Left				
Image: second participation of the		1912111	5111151				101123				1110				
Design Method In a frame of book for Start Racing Of Parkase A of Control Second A of Control Second A of Control A of Contro A of Contro A of Control				lext											
Design Method In a frame of book for Start Racing Of Parkase A of Control Second A of Control Second A of Control A of Contro A of Contro A of Control															
Design Method In a frame of book for Start Racing Of Parkase A of Control Second A of Control Second A of Control A of Contro A of Contro A of Control	~				0	ontorlino									
a. Unit Type: Develope of belations Surget Partial 300 (2000) 660 (2000) 1 Surget Partial 300 (2000) 660 (2000) 660 (2000) 2 One in Linit 300 300 300 (2000) 660 (2000) 2 One in Linit 300 300 300 (2000) 660 (2000) 4 Deleter Calcination					U U	entenine									
Lam Data Data <th< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td>Lin</td><td>e Flament m</td><td>ethad</td></th<>									Lin	e Flament m	ethad				
2 Ourse Lath 26 30															
Add Edit Delete Calculate															
€ Coordinates List term barlin terminic Annum ss 0x100 5 0 arrwan ss 0x100 5.6 0 arrwan st 0x100 5.6 0 arrwan st 0x100 5.6 0 247279.27.11 0x100 4.872 4.91 0 247279.27.11 0x100 4.02 0 247279.27.11 0 0x100 4.02 0 247279.27.11 0 1 0x000 1.02 24729.22.11 0 24729.23.11 1 0x000 1.02 1.02 0 3144 245 1 1.000 4 0 0 1.05 0 3144 1 1.000	2 1	Curve	Left	30	30	55 36	-30-201	669.000							
€ Coordinates List term barlin terminic Annum ss 0x100 5 0 arrwan ss 0x100 5.6 0 arrwan st 0x100 5.6 0 arrwan st 0x100 5.6 0 247279.27.11 0x100 4.872 4.91 0 247279.27.11 0x100 4.02 0 247279.27.11 0 0x100 4.02 0 247279.27.11 0 1 0x000 1.02 24729.22.11 0 24729.23.11 1 0x000 1.02 1.02 0 3144 245 1 1.000 4 0 0 1.05 0 3144 1 1.000															
€ Coordinates List term barlin terminic Annum ss 0x100 5 0 arrwan ss 0x100 5.6 0 arrwan st 0x100 5.6 0 arrwan st 0x100 5.6 0 247279.27.11 0x100 4.872 4.91 0 247279.27.11 0x100 4.02 0 247279.27.11 0 0x100 4.02 0 247279.27.11 0 1 0x000 1.02 24729.22.11 0 24729.23.11 1 0x000 1.02 1.02 0 3144 245 1 1.000 4 0 0 1.05 0 3144 1 1.000															
€ Coordinates List term barlin terminic Annum ss 0x100 5 0 arrwan ss 0x100 5.6 0 arrwan st 0x100 5.6 0 arrwan st 0x100 5.6 0 247279.27.11 0x100 4.872 4.91 0 247279.27.11 0x100 4.02 0 247279.27.11 0 0x100 4.02 0 247279.27.11 0 1 0x000 1.02 24729.22.11 0 24729.23.11 1 0x000 1.02 1.02 0 3144 245 1 1.000 4 0 0 1.05 0 3144 1 1.000															
Barnis Northing Daring Barnis Northing Daring Barnis Northing Barnis Northing Barnis Northing 99 47000 5 6 0 3470070 -		Add		Ec	lit	Dele	rte		Calcula	ite					
Barnis Northing Daring Barnis Northing Daring Barnis Northing Barnis Northing Barnis Northing 99 47000 5 6 0 3470070 -															
SP 49/200 5 6 0 37/2010 1 1 0 37/2010 1 1 0 37/2010 1 1 0 37/2010 1 1 0 37/2010 1 1 0 37/2010 1 1 0 37/2010 1 1 0 37/2010 1 1 0 37/2010 1 1 0 37/2010 1 1 0 37/2010 1 1 0 37/2010 1 1 0 37/2010 1 1 0 37/2010 1 1 0 37/2010 1 <th1< th=""> 1 1 <th1< th=""></th1<></th1<>	←				Coo	rdinates l	ist								
SP 49/200 5 6 0 37/2010 1 1 0 37/2010 1 1 0 37/2010 1 1 0 37/2010 1 1 0 37/2010 1 1 0 37/2010 1 1 0 37/2010 1 1 0 37/2010 1 1 0 37/2010 1 1 0 37/2010 1 1 0 37/2010 1 1 0 37/2010 1 1 0 37/2010 1 1 0 37/2010 1 1 0 37/2010 1 <th1< th=""> 1 1 <th1< th=""></th1<></th1<>	lame	Station	Northing	Easting E	Deration	Azimuth									
Carl 57.000 31.645 0.036 0.03723/26.1647 0.036 32623/26.1647 0.0367															
02.00 34.45 6.30 0 354.737 702° 02.00 43.74 411 0 397 376 256 254° PP 75.60 50.91 4.41 0 397 1753 367° Chulde Mode Vertical Profile Database Crude core Crude core 2 30.00 4 2 0 364.737 702° 2 30.00 4.74 0 397 1753 367° 4.747 707 1757 367° 2 3.000 4 2 0 361.757 702° 1.757 55 2 4.000 3.15 5.589 -1.575 5 4.42 3.26 3 755.000 4.3 2 3.00 4.56 3.272 3 175.000 4.4 3.2 3.0 4.44 3.26 3 175.000 4.0 3.0 4.944 3.26 3.272 Charler Rod Design Vertical Profile Vertical Profile 2.2 3.2 Charler Instent atation 2.2 2	80.00	680.000	14.873	10.708	0 14	59'29.571'									
10000 42.00 42.00 42.00 9.0000 42.00 9.0000 42.00 9.00000 9.00000 9.00000 9.00000 9.00000 9.00000 9.00000 9.00000 9.00000 9.000000 9.000000 9.000000 9.0000000 9.000000000000000000000000000000000000			31.643	10.345	0 342	31'26.1808'									
PP 25.000 50.91 4.44 0 2017/05/2.0172 Calculate Mode Vertical Profile Database Civular uner Civular uner Civular uner 0 35.000 4 48 0 1.515 0.277 1 35.000 4 48 0 1.515 0.272 2 48.00 3.5 1.93 5.99 1.515 0.272 Insert Edit Delete Import OK Rost Name Edit Delete Import OK Stop sector Library Check OK Civular uner Civular uner Stop sector Library Check Delete Import OK		657.000													
Note Vertical Profile Database Calculate Mode Croute area a: Step point nation: Step into into into into into into into into	смт			9.302	0 336	47'39.7002'									
Calculate Mode Crudie cave Crudie cave a: Stapp point national listope point national interactional interactinteractione interactional interactional interactional interactiona	СМ1 00.00	700.000	34.455												
a. Stoppoor statow issue sport stops in instate sport large in the sport large in th	СМ1 00.00 20.00	700.000 720.000	34.455 48.974	-5.911	0 298	35'49.8294'									
1 35.000 4 36 0 1.5.15 0.272 2 68.000 3.5 1.55 5.690 1.5.15 4.644 2.85 3 736.000 4 92 3 4.944 2.85 1 1.55 6.690 1.555 4.944 2.85 1 1.681 Delete Import OK Road Design Road Name Road Design Centerine C Standed Oras Berline C Standed Oras Berline C Standed Oras Berline C Map Cheek C Map Type Centertine	CM1 00.00 20.00 FP	700.000 720.000	34.455 48.974	-5.911	0 298	10752 361 7°	tabas	e							
2 64.00 3.3 135 54.9 1.51 64.64 2.85 3 173.00 -4 92 3 4.94 0 3.14 Insert Edit Detern Import OK Road Dasign Road Dasign	см1 00.00 20.00 FP	700.000 720.000 725.000	34,455 48,974 50,991	-5.911	0 298 0 289 Vertical F	9549.8294 10792.3617 Profile Da									
Name Edit Delete Import OK Road Name Road Design Canada	см1 00.00 20.00 FP Саю	700.000 720.000 725.000	34,455 48,974 50,991 de	-3.911 -8.48	0 298 0 289 Vertical I	"3549.8294" "0752.3617" Profile Da	gth Sia	pe 1(%) :		Targent Lo					
Insert Edit Delete Import OK Construction Construction Construction Construction Construction Statused Construction Construction Construction Construction Construction Statused Construction Construction Construction Construction Construction Map Type Construction Construction Construction Construction	смт 20.00 FP Саю	700.000 720.000 725.000	34,455 48,974 50,991 de	-3.911 -8.48	0 298 0 289 Vertical I	10/52 361 7 10/52 361 7 Profile Da us. Sprai len 0	gth Sia	pe 1(%) : 0	-1.515	Targent Les 0.273					
Road Design Road Name sc ☉ Road Name sc ☉ Centarine 20 Centarine 20 Starded Cross Section 20 Slope sectors Library 20 Map Check OK 100 Map Check Map Check OK 100	CM1 00.00 20.00 FP Calci 0. Sit	700.000 720.000 725.000 ulate Moo per point s 25.000	34,455 48,974 50,991 de datator SI	-3.911 -8.48 ope point d -4 -3.5	0 296 0 289 Vertical f	10/52 361 7 10/52 361 7 Profile Da us. Sprai len 0	gth Sia	pe 1(%) : 0	-1.515	Targent Les 0.273					
Road Design Road Atame sc Road Atame sc It forker station > Centerine > Centerine > Standard Cross Section > Stops sectors Library > Map Check OK	CM1 00.00 20.00 FP Calci 1 1 2	703.000 723.000 725.000 ulate Moc spe point s 85.030 68.030	34,455 48,974 50,991 le tator SI	-3.911 -8.48 ope point d -4 -3.5	0 296 0 289 Vertical I levation Ratio 36 103	13549 82941 10752 361 7 Profile Da us. Spratien 0 5 5 5889	gth Sia	pe 1(%) : 0 1.515	-1.515 -6.944	Targent Lee 0.273 2.85					
Road Design Road Atame sc Road Atame sc It forker station > Centerine > Centerine > Standard Cross Section > Stops sectors Library > Map Check OK	CM1 00.00 20.00 FP Calci 1 1 2	703.000 723.000 725.000 ulate Moc spe point s 85.030 68.030	34,455 48,974 50,991 le tator SI	-3.911 -8.48 ope point d -4 -3.5	0 296 0 289 Vertical I levation Ratio 36 103	13549 82941 10752 361 7 Profile Da us. Spratien 0 5 5 5889	gth Sia	pe 1(%) : 0 1.515	-1.515 -6.944	Targent Lee 0.273 2.85					
Read Hanne de Co E Inden station C cesterine C cesterine S Standed Cross Section Map Check OK Preview Map r Preview Map C	CM1 00.00 20.00 FP Calor Calor 1 2	703.000 723.000 725.000 ulate Moc spe point s 85.030 68.030	34,455 48,974 50,991 le tator SI	-3.911 -8.48 ope point d -4 -3.5	0 296 0 289 Vertical I levation Ratio 36 103	13549 82941 10752 361 7 Profile Da us. Spratien 0 5 5 5889	gth Sia	pe 1(%) : 0 1.515	-1.515 -6.944	Targent Lee 0.273 2.85					
Read Hanne de Co E Inden station C cesterine C cesterine S Standed Cross Section Map Check OK Preview Map r Preview Map C	CM1 00.00 20.00 FP Calco 1 2 3	700.000 720.000 725.000 1725.000 1725.000 175.000 175.000	34.455 48.974 50.991	-3.911 -8.48 ope ptint d 4 3.5 -4	0 299 0 289 Vertical I levation Ratio 36 103 92	10752 361 7 Profile Da us: Spratien 0 5 5 669 0	gth Sia	pe 1(%) : 0 1.515 6.944	-1.515 -6.944 0	Targent La 0.273 2.85 3.194	igth				
	CM1 00.00 20.00 FP Calco 1 2 3	700.000 720.000 725.000 1725.000 1725.000 175.000 175.000	34.455 48.974 50.991	-3.911 -8.48 ope ptint d 4 3.5 -4	0 299 0 289 Vertical I levation Ratio 36 103 92	10752 361 7 Profile Da us: Spratien 0 5 5 669 0	gth Sia	pe 1(%) : 0 1.515 6.944	-1.515 -6.944 0	Targent La 0.273 2.85 3.194	igth				
	CM1 00.00 20.00 FP Calco 1 2 3	700.000 720.000 725.000 1725.000 1725.000 175.000 175.000	34.455 48.974 50.991	-3.911 -8.48 ope ptint d 4 3.5 -4	0 296 0 289 Vertical I ievation Radii 36 109 92	Profile Da us Sprat len 6 5 5 689 0 Delete	gth Sia	pe 1(%) : 0 1.515 6.944	-1.515 -6.944 0	Targent La 0.273 2.85 3.194	igth				
	CM1 00.00 20.00 FP Calor 0. Sit 1 2 3 	700.000 720.000 725.000 725.000 725.000 900 900 900 900 900 900 900 900 900	34.455 48.974 50.991	-3.911 -8.48 ope ptint d 4 3.5 -4	0 296 0 289 Vertical I ievation Radii 36 109 92	Profile Da us Sprat len 6 5 5 689 0 Delete	gth Sia	pe 1(%) : 0 1.515 6.944	-1.515 -6.944 0	Targent Lo 0.273 2.85 3.194					
Versical Postfer Versical Postfer Versical Postfer Versical Postfer Versical Postfer Storp action Storp action Storp action Storp action Storp action Storp action Cherok OK Preview Map Type Cervariae	CM1 00.00 20.00 FP Calco 0. Sk 1 2 3 Calco 0. Sk 1 2 3 Calco 0. Sk 1 2 3 Calco 0. Sk 1 2 3 Calco 0. Sk 1 2 3 Calco 0. Sk 1 2 3 Calco 0. Sk 1 2 3 Calco 0. Sk 1 Calco Calco Calco Calco Calco Calco Calco Calco Calco Calco Calco Calco Calco Calco Calco Calco Calco Calco	700.000 720.000 725.000 2755.000 255.000 255.000 175.000 175.000 175.000	34.455 43.974 50.991	-3.911 -8.48 ope ptint d 4 3.5 -4	0 296 0 289 Vertical I ievation Radii 36 109 92	Profile Da us Sprat len 6 5 5 689 0 Delete	gth Sia	pe 1(%) : 0 1.515 6.944	-1.515 -6.944 0	Targent Lo 0.273 2.85 3.194	agth				
	CM1 00.00 20.00 FP Calor 0. Sile 1 2 3 Calor 0. Sile 1 2 3 Calor 0. Sile 1 2 3 Calor 0. Sile 1 2 3 Calor 0. Sile 1 2 3 Calor 0 Calor Calor Calor 0 Calor 0 Calor Cal	700.000 720.000 725.000 175.000 175.000 175.000 175.000 175.000 175.000	34.455 43.974 50.991	-3.911 -8.48 ope ptint d 4 3.5 -4	0 296 0 289 Vertical I ievation Radii 36 109 92	Profile Da us Sprat len 6 5 5 689 0 Delete	gth Sia	pe 1(%) : 0 1.515 6.944	-1.515 -6.944 0	Targent Lo 0.273 2.85 3.194	agth				
Slope sectors Library Map Check OK Proview Map wm Type Curstine	Смп 00.30 20.30 20.30 Саłса 0. Słk 1 2 3 Саłса 0. Słk 1 2 3 Саłса 0. Słk 1 2 3 Саłса 0. Słk 1 2 3 Саłса 0. Słk 1 2 2 3 Саłса 0 Саłса 0 Саłса 0 Саłса 1 2 2 2 3 Саłса 0 Саłса 0 Саłса 0 Саłса 1 2 Саłса 0 Саłса 0 Саłса 0 Саłса 1 Саłса 0 Саłса 0 Саłса 0 Саłса 0 Саłса 0 Саłса 0 Саłса 0 Саłса 0 Саłса Са́са С	700.000 720.000 775.000 775.000 80.000 175.000 175.000 175.000 175.000 175.000 175.000 175.000 175.000 175.000 175.000	34.455 48.974 50.991 de tatator 31 3 3 3 4 4 8 4 8 4 8 4 8 4 8 4 8 4 8 4 8	-3.911 -8.48 ope ptint d 4 3.5 -4	0 296 0 289 Vertical I ievation Radii 36 109 92	Profile Da us Sprat len 6 5 5 689 0 Delete	gth Sia	pe 1(%) : 0 1.515 6.944	-1.515 -6.944 0	Targent Lo 0.273 2.85 3.194	agth				
Map Check OK Preview Map m Map Type Centrine	Смп 00.30 20.30 20.30 Саłса 0. Słk 1 2 3 Саłса 0. Słk 1 2 3 Саłса 0. Słk 1 2 3 Саłса 0. Słk 1 2 3 Саłса 0. Słk 1 2 2 3 Саłса 0 Саłса 0 Саłса 0 Саłса 1 2 2 2 3 Саłса 0 Саłса 0 Саłса 0 Саłса 1 2 Саłса 0 Саłса 0 Саłса 0 Саłса 1 Саłса 0 Саłса 0 Саłса 0 Саłса 0 Саłса 0 Саłса 0 Саłса 0 Саłса 0 Саłса Са́са С	700.000 720.000 775.000 775.000 80.000 175.000 175.000 175.000 175.000 175.000 175.000 175.000 175.000 175.000 175.000	34.455 48.974 50.991 de tatator 31 3 3 3 4 4 8 4 8 4 8 4 8 4 8 4 8 4 8 4 8	-3.911 -8.48 ope ptint d 4 3.5 -4	0 296 0 289 Vertical I ievation Radii 36 109 92	Profile Da us Sprat len 6 5 5 689 0 Delete	gth Sia	pe 1(%) : 0 1.515 6.944	-1.515 -6.944 0	Targent Lo 0.273 2.85 3.194	sgth				
Preview Map mm mp Type Centratine	См1 00.30 25.30 FP Сайон с Sik 1 2 3 Козай Сайон Сай	700.000 720.000 725.000 reperint a 55.000 reperint a 55.000 reperint a 55.000 reperint a 55.000 reperint a 55.000 reperint a 5.000 reperint a 5.0000 reperint a 5.00000 reperint a 5.0000 reperint a 5.0000 reperint a 5.0000 reperint a 5.0000 reperint a 5.00000 reperint a 5.00000 reperint a 5.00000 reperint a 5.00000 reperint a 5.000000000 reperint a 5.000000000000000000000000000000000000	34.455 48,974 50.991 6 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9	4 3911 8 48 3.5 -4 Edit	0 296 0 289 Vertical I ievation Radii 36 109 92	Profile Da us Sprat len 6 5 5 689 0 Delete	gth Sia	pe 1(%) : 0 1.515 6.944	-1.515 -6.944 0	Targent Lo 0.273 2.85 3.194	agih				
Preview Map map Type Curistine	сыл 20.00 20.00 FP Сайо сайо 1 2 3 Коаd Ф Ф	703.000 723.000 725.000 responses 35.000 responses 175.000 responses 175.000 responses 175.000 responses 175.000 responses response response response responses responses responses respon	34.455 43.974 43.974 50.991 4 4 4 4 4 4 50.991 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	oope paint of a 3 911 a 4 3 a 4 a 5 a 4 Edit Edit	0 296 0 289 Vertical I ievation Radii 36 109 92	23549.5294 270752.3617 Profile Da us Spratien 0 5 5 5 6 8 0 0 Delete	gth Sia	pe 1(%) : 0 1.515 6.944	-1.515 -6.944 0	Targent Lo 0.273 2.85 3.194	agih				
Map Type Centerline	сыл 20.00 20.00 FP Сайо сайо 1 2 3 Коаd Ф Ф	703.000 723.000 725.000 225.000 255.0000 255.0000 255.0000 255.0000 255.0000 255.0000 255.0000 255.0000 255.0000 255.0000 255.0000 255.0000 255.00000 255.0000000000	34.455 43.974 50.991	oope paint of a 3 911 a 4 3 a 4 a 5 a 4 Edit Edit	0 296 0 289 Vertical I ievation Radii 36 109 92	33994 5294* 33994 5294* 27cofile Da as Spontiered a 3 5 5 5 5 8 9 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	gth Sia	pe 1(%) : 0 1.515 6.944	-1.515 -6.944 0	1273 2.273 2.273 2.245 2.194 2.194	agih				
Map Type Centerline	сыл 20.00 20.00 FP Сайо сайо 1 2 3 Коаd Ф Ф	703.000 723.000 725.000 225.000 255.0000 255.0000 255.0000 255.0000 255.0000 255.0000 255.0000 255.0000 255.0000 255.0000 255.0000 255.0000 255.00000 255.0000000000	34.455 43.974 50.991	oope paint of a 3 911 a 4 3 a 4 a 5 a 4 Edit Edit	0 296 0 289 Vertical I ievation Radii 36 109 92	33994 5294* 33994 5294* 27cofile Da as Spontiered a 3 5 5 5 5 8 9 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	gth Sia	pe 1(%) : 0 1.515 6.944	-1.515 -6.944 0	1273 2.273 2.273 2.245 2.194 2.194	agih				
	сыл 20.00 20.00 FP Сайо сайо 1 2 3 Коаd Ф Ф	703.000 723.000 725.000 225.000 255.0000 255.0000 255.0000 255.0000 255.0000 255.0000 255.0000 255.0000 255.0000 255.0000 255.0000 255.0000 255.00000 255.0000000000	34.455 43.974 50.991	oope paint of a 3 911 a 4 3 a 4 a 5 a 4 Edit Edit	0 2969 0 2969 Vertical 9 484 492 92 Rox	1999 504 504 7 1075 341 7 Profile Da a 5 5.569 0 Delete ad Design	- -	pe 1(%) : 0 1.515 6.944	-1.515 -6.944 0	1273 2.273 2.273 2.245 2.194 2.194	agih				
ter de la constante de la const La constante de la constante de	сыл 20.00 20.00 FP Сайо сайо 1 2 3 Коаd Ф Ф	703.000 723.000 725.000 225.000 255.0000 255.0000 255.0000 255.0000 255.0000 255.0000 255.0000 255.0000 255.0000 255.0000 255.0000 255.0000 255.00000 255.0000000000	34.455 43.974 50.991	oope paint of a 3 911 a 4 3 a 4 a 5 a 4 Edit Edit	0 2969 0 2969 Vertical 9 484 492 92 Rox	1999 504 504 7 1075 341 7 Profile Da a 5 5.569 0 Delete ad Design	- -	pe 1(%) : 0 1.515 6.944	-1.515 -6.944 0	Тагден I.d. 0.273 2.85 1.164 ОК	sz 😒				
Can Les Les	CMT 00.00 20.00 FP Calo C	700.000 723.000 725.000 725.000 725.000 725.000 83.50000 83.50000 83.50000 83.50000 83.5000000000000000000000000000000000000	34.455 43.974 50.991	oope paint of a 3 911 a 4 3 a 4 a 5 a 4 Edit Edit	0 2969 0 2969 Vertical 9 484 492 92 Rox	1999 504 504 7 1075 341 7 Profile Da a 5 5.569 0 Delete ad Design	- -	pe 1(%) : 0 1.515 6.944	-1.515 -6.944 0	Тагден I.d. 0.273 2.85 1.164 ОК	sz 😒				
4. St.	CMT 00.00 20.00 FP Calo C	700.000 723.000 725.000 725.000 725.000 725.000 83.50000 83.50000 83.50000 83.50000 83.5000000000000000000000000000000000000	34.455 43.974 50.991	oope paint of a 3 911 a 4 3 a 4 a 5 a 4 Edit Edit	0 2969 0 2969 Vertical 9 484 492 92 Rox	1999 504 504 7 1075 341 7 Profile Da a 5 5.569 0 Delete ad Design	- -	pe 1(%) : 0 1.515 6.944	-1.515 -6.944 0	Тагден I.d. 0.273 2.85 1.164 ОК	ugth				
	CMT 00.00 20.00 FP Calo C	700.000 723.000 725.000 725.000 725.000 725.000 83.50000 83.50000 83.50000 83.50000 83.5000000000000000000000000000000000000	34.455 43.974 50.991	oope paint of a 3 911 a 4 3 a 4 a 5 a 4 Edit Edit	0 2969 0 2969 Vertical 9 484 492 92 Rox	1999 504 504 7 1075 341 7 Profile Da a 5 5.569 0 Delete ad Design	- -	pe 1(%) : 0 1.515 6.944	-1.515 -6.944 0	Тагден I.d. 0.273 2.85 1.164 ОК	ugth				

You can toggle to view a preview of the vertical profile.

Click the [OK] button in the lower right corner of the road design interface, the instrument returns to the "Stake road by point" interface, and the newly created roads have been displayed on the screen

Tap the road on the screen and tap the Apply button.

The instrument enters the stakeout settings interface, and after the setting is completed, click the [OK] button at the bottom.

The instrument enters the stakeout interface, and then please collimate the prism and proceed with the stakeout operation. For more information, see also **chapter 6.10 point stakeout**.

Stake road by point Nervar Pedelinned BrangeSurPaciProget2020508/04/04e Nervar Nervar Nervar Nervar Nervar

Pre

Мар Тург







7. Check and Adjustment

7.1 The Instrument Constant

1) Check

It is suggested to observe and compare the instrument with a testing line which is set on stable ground with a particular accuracy, though error is not generally included in the instrument constant. If the testing line is unavailable, you can set it for 20 meters or so by yourselves, then check and compare it with your new instrument.



1. Select a point B on the approximately horizontal line AC with about 100 meters long. Measure the distances of lines AB , AC and BC .

2. The instrument constant can be calculated;

instrument constant =AB+BC-AC

3. If there is a difference between the instrument standard constant and the calculated value, colligate the measured constant and the prism constant to get a new value, then input the value into the instrument as a prism constant.

4. Compare length of the instrument's testing line again with a certain standard testing line.

5. If the difference is over 5 mm after the preceding operations, it is necessary to reset the instrument constant.

2) Adjustment

About instrument constant setting, you must contact ALPHA distributor to do that.

7.2 Plate Level and Circular Level

7.2.1 Plate Level

1) Check

1. Mount the instrument on a stable device (as tripod , adjusting device), and fix it.

2. Level the instrument until the plate level is parallel to a line linking leveling foot screws A and B, then adjust the two screws to center the air bubble.

3. Turn the instrument 180°, observe the moving direction of the bubble, if it is still centered, no adjustment is necessary, if not, you have to adjust it.

2) Adjustment

1. Mount the instrument on a stable device and fix it.

2. Level it roughly.

3. Turn the instrument and make the plate level be parallel to a line linking two leveling foot screws, then adjust the two screws to center the air bubble .

4. Turn the instrument 180°, adjust the Adj-screw with adjustment pin slightly to correct half of the bubble's displacement when it doesn't move,
5. Repeat the exercise (2) and (4) until the air bubble remains contored in

5. Repeat the operation (3) and (4) until the air bubble remains centered in any position.



Turnthe instrument 180°



7.2.2 Circular Level

1) Check

1. Mount the instrument on a stable device and fix it.

2. Level it accurately by the plate level.

3. Observe the bubble of the circular level, if it is centered, no adjustment is necessary, if not, you have to adjust it.

2) Adjustment

4. Mount the instrument on a stable device and fix it.

5. Level it accurately by the plate level.

6. Adjust the three adjusting screws to center the bubble by a wrench.

Note: Be careful when adjusting the

three screws, and the tightening tension is identical for them.





7.3 The Optical Sight

Check

1. Mount the instrument on a tripod and fix it.

2. Set a cross mark target which apart from the instrument about 50m.

3. Take the telescope sight the cross mark.

4. Observe the optical sight collimator whether collimating the cross mark, if collimate the mark, adjustment is not necessary; if not, adjust it.





Adjustment

- 1. Mount the instrument at the tripod and fix it.
- 2. Set a cross mark target which apart from the instrument about 50m.
- 3. Take the telescope sight the cross mark.
- 4. Loosen two fixing screws, adjust the collimator, then fix the two screws again.

7.4 Laser Plummet

1) Check

(1)Set the instrument on stable device and fix it.

(2)Set a cross mark on the ground under the instrument.

(3) Turn the laser switch on and focus it accurately.

(4)Turn the three leveling screws until the instrument keeps leveling and the laser spot coincides with the cross mark on the ground.

(5)Rotate the instrument 180°(200g) around and check the laser spot and

cross mark, if they coincide, adjustment

is not required. Otherwise, adjust it.

2) Adjustment

1. Setting up the instrument on the checking tool or tripod which is 1.5m apart from ground.

2. Turn on laser plummet, turn tribrach foot screws until laser spot coincide with

cross mark. If you use tripod, make a cross mark on the laser spot directly. 3. Rotate instrument 180° around, if the laser spot is over 2mm apart from cross mark, remove the protecting cover firstly, adjust two screws with 1.5mm hexagon wrench to move laser spot to the cross mark, correct only

one-half of the displacement in this manner.

Adjusting details see attached figure. 4. Repeat steps 2 and 3 until laser spot coincides with cross mark always when rotate instrument.

Note: there are three screws amounted around laser plummet part, only two screws are used for laser accuracy adjustment.



Protecting cover fixing screw

Un-adjustable Adjustable screw screw



7.5 Vertical Cross-hair on Telescope

1) Check

(1) Set the instrument up the tripod and carefully level it.

(2) Set a point A front the instrument 50m apart;

(3) Collimate the point A and adjust the vertical tangent screw; If the point appears to move continuously on the hair, adjustment is not required. Otherwise, adjust it.



2) Adjustment

(1) Set the instrument, and set the point A front the instrument 50m apart.

(2) Take off cover of telescope eyepiece, there are 4 screws for the reticle part.



(3) Loosen all four fixing screws slightly with the cross screw-drive.

(4) Revolve the eyepiece section so that the vertical cross-hair coincides to

point A, finally, re-tighten the four screws.

(5) Repeat the checking and adjusting until there is no deviation.

NOTE:

1) After the adjustment of cross-hair, please check the collimation error and vertical index error.

7.6 Horizontal Collimation Error C

If the telescope's sight line isn't perpendicular to the horizontal axis, the collimation error will appear. The assembling, transportation and operation will cause this error.

If the collimation error isn't over the permitted range, with the program the instrument can correct this collimation error.

NOTE: After the program correction this deviation error is also on the instrument.

1) Check

(1) Set-up the instrument on tripod or adjustment platform and leveling accurately.

(2) Aim at the cross-hairs of collimator or the obvious target at a distance. Get the face left angle reading H1 and the face right angle reading Hr.

(3) Calculating the horizontal collimation error C according to C= (Hl-

Hr±180°) /2,if C<8", no adjustment will be necessary. If C>8", proceed with the following adjustment.

2) Adjustment by program:

Please refer to chapter 4.3 Calibrate the collimation error and index error

Note:

The adjustment can be performed by the program when C<30", if C>30", adjust the reticle.

Reticle Adjusting:

1. Rotate the instrument in face right position, turning horizontal tangent screw until Hr'=Hr+C.



 Adjusting two screws at left and at right until the vertical hairs of telescope's reticle coincides with the cross-hairs of collimator or target.
 Repeat the check and adjustment procedure until the error is accepted.

NOTE:

 When adjust the screws of reticle, firstly loosen the screw on the moving direction of reticle, secondly tighten another screw by the same mount, clockwise turning is for tightening, and anticlockwise turning is for loosening, the turning mount for tightening or loosening should be same.
 After the reticle adjustment, it is necessary to adjust the vertical index error by program.

7.7 Vertical Index Error

The deviation between vertical circle zero position and horizontal direction is vertical index (i), it is necessary to concern this error when measure vertical angle. The instrument program applied a formula to remove this error. This correction can offer the index for the formula. Warning: Before starting this operation, be sure to read manual carefully, otherwise it may cause data faulty.

Because of the close relationship between vertical index and compensator zero position, it is necessary to check and adjust compensator zero position when adjust the vertical circle, the value should be stable when reading. 1) Check: Please adjust the reticle of telescope and correct the collimation error before this operation.

(1) Mount the instrument at the tripod or a stable device and level it accurately, then turn on the instrument.

(2) Aim at the cross-hairs of collimator or the obvious target at a distance,

VA should be about $\pm 10^{\circ}$. Read the face left angle VI and face right angle Vr.

(3) Calculate the index error according to the formula below:

i = (VI+Vr-360°)/2

(4)If I<10 $^{\prime\prime}\,$, no adjustment is necessary , or you have to adjust it .

2) Adjustment by program:

Please refer to chapter 4.3 Calibrate the collimation error and index error

8 Specification

Telescope

Image	: Erect
Magnification	: 30×
Aperture	: 45mm
Resolution	: 3.75″
Field of view	: 1°30′
Minimum focus	: 1.0m

Angle measurement

Reading system	Absolute encoder
Circle diameter	: 79mm
Min. display	: 0.01" / 0.1" / 1"
Detecting way	: Double for H and V
Accuracy	: 2"

Distance measurement

Target		
No-prism	: 1km	
Reflector(60×60mm)	: 1km	
Prism	: 5km	
Accuracy	prism	: ±(2+2×10 ⁻⁶ ·D)mm
	Reflector	: ±(2+2×10 ⁻⁶ ·D)mm
	No-prism	: ±(2+2×10 ⁻ •D)mm
Measuring time		: Single fine 1.0s, tracking 0.3s
Meteorological corrections		: The input parameters realize correction or the sensors in the machine realize automatical correction

Correction for atmospheric refraction and Earth curvature : The input parameters realize correction K=0.14/0.2optional

The reflective prism constant correction :The input parameters realize correction

Level

Plate level	:	30" / 2mm
Circular level	:	8′ / 2mm

Tilt correction

	Туре	: Automatic vertical and horizontal angles
	Compensation method Range Resolution	: Liquid capacitive : ±3' : 1"
Plumm		
	Туре	: Laser
	Accuracy	: ±8mm/0.6~1.5m
	Wavelength	: 635nm
	Working range	: 0.5~80m
		: Class2
	Max. output power	: 0.7~1.0mW
Syste	em	
-,		ID11.0(supports cloud update, APP update, etc.)
CPU	Туре	:Quad-core 2GHZ
	туре	
Disp	lay	
	Туре	:Both-side 5.5 inch LCD 1280*720
		Touch color capacitive display
Mer	nory	
iner	•	
	Capacity	:4GRAM+32GROM(8GRAM+128GROM optional)
Data	a transfer	
Dute		
	Port :RS-232C,	USB HOST, USB Type_C, Bluetooth, WIFI, SIM(optional)
Net	work	
	Туре	: Full netcom (4G optional)
	••	· ·

Battery

Power	: Lithium battery
Voltage	: DC 7.2V
Capacity	: 5.2Ah 37.44Wh
Working hours	: >8h (angle and distance measurements every 30S at 25°C)
	: >12h (only angle measurement at $25^{\circ}C$)

Environment

Operating	:	$-20^{\circ}\mathrm{C}{\sim}+50^{\circ}\mathrm{C}$
Protection grade	:	IP 55

Size & weight

Size	: 185mm×230mm×360mm (including handle)
Weight	: <5.5kg (including handle, battery and tribrach)

Appendix 1 : Atmospheric Correction Formula and Atmospheric Correction Diagram (for reference only)

```
Standard values for instrument settings:

temperature 20°C, air pressure 1013hpa,0ppm

Atmospheric correction value is:

Kpt=278.960-0.2902*p/(1+0.0036*t)

where :

p-- air pressure value(hpa)

t-- temperature (°C)

Kpt-- Atmospheric correction value (ppm)

example:

t=20°C, p=1013hpa, L0=1000m.

Then: Kpt=4ppm

L=L0(1+Kpt)=1000×(1+4×10<sup>-6</sup>)=1000.004m
```

The atmospheric value is obtained easily with the atmospheric correction chart. Find the measured temperature in horizontal axis, and pressure in vertical axis on the chart.

Read the value from the diagonal line, which is the required atmospheric correction value.







Elevation (m)

Appendix 2 :Corrections for atmospheric refraction and the curvature of the Earth

Considering the ranging error caused by atmospheric refraction and the curvature of the earth, the instrument calculates the slope distance, horizontal distance and elevation difference according to the following formula, and automatically adds the earth curvature difference and the average atmospheric refractive correction (K=0.14 or 0.20). The average calculation is relative to the occupied station elevation, not the prism station elevation.

 $SD=D_0 \times (1+ppm \times 10^{-6}) + mm$

SD--displayed slope distance (m)

 D_0 -- uncorrected distance (m)

ppm--Proportional correction factor(mm/km)

mm-- prism constant (mm)

HD=Y-A×X×Y

 $VD = X + B \times Y^2$

```
HD--horizontal distance (mm)
```

```
VD—height difference (mm)
Y = SD*ISinI ξ
X = SD*Cosξ
ξ—— zenith reading
```





K = 0.142 or 0.20

$$R = 6.37 \times 10^6 (m)$$

If the ranging error caused by atmospheric refraction and the curvature of the earth is not considered, the formula for calculating the horizontal distance HD and the vertical distance VD is as follows:

Note: The atmospheric refractive coefficient of the instrument has been set to 0.142 before leaving the factory.

Appendix 3 :Disassembly of the tribrach

By loosening or tightening the lock lever knob, the instrument can be easily removed from the tribrach or mounted onto the tribrach.

• Dismount the instrument

(1) Rotate the tribrach knob in a counterclockwise direction to loosen the lock lever.

(2) Hold the instrument handle with one hand and the tribrach with the other hand, and take out the instrument upwards.

• Mount the instrument

(1) Hold the instrument handle with one hand and place the instrument on the tribrach, and align the lower alignment piece with the tribrach alignment groove.(2) Rotate the lock lever knob of tribrach clockwise to tighten the lock lever.



• Tighten the lock lever knob of tribrach

The lock lever knob of tribrach can be locked to prevent it from being unscrewed inadvertently. This function is necessary if the upper part of the instrument does not need to be assembled and disassembled frequently. Simply use an accessory screwdriver to unscrew the insurance screw in the hole of the lock lever knob.

NOTE:

These designs, figures and specifications are subject to change without notice. We shall not be held liable for damages resulting from errors in this instruction manual.